Bluetooth Headset user Guide

Rev1109

AA-2080

Specifications:

Model Number: AA-2080
Signal Output: *Bluetooth* v2.1, Class 2
Talk Time: Up to 13 hours
Standby Time: Up to 220 hours
Standard Charge Time: Up to 3 hours
Profiles: Headset & Handsfree
Connections: Up to 2 devices simultaneously
Data Encryption: 128 bits encrypted

Overview:
Thank you for purchasing this headset. Please check the contents of the packaging to verify that you have received all items. Be sure the completely read the user guide before using the headset. This headset can be connected/paired with any device that is *Bluetooth* wireless technology enabled.

Getting Started:
Please charge the headset for 10 hours before first time use.

Troubleshooting:
* Ensure that the headset has enough power, is turned on, and has successfully been fully paired with the mobile device.
* Ensure that the *Bluetooth* function on the phone is enabled.
* Be sure that the range between the headset and mobile device is less than 32 feet (10 metres), or that there is no disturbances or electrical devices between the headset and mobile device.
* Headset indicator light is flashing red: Low battery
* During charging indicator light does not illuminate: Leave on charger for 20 more minutes and re-check.
* No sound coming from headset: 1. Make sure headset is turned on, 2. Make sure headset was fully paired, 3. Make sure distance between headset and device is less than 32 feet.

Headset Storage:
* Only use original included accessories with this device.
* Do not disassemble headset. It will void the warranty.
* Store headset away from dust, heat, and water.
* Use clean, soft, static-free cloth to clean headset surfaces.
* Do not allow children to play or use headset.
* Do not store headset or chargers in extreme environments.

Pairing the Headset:
Pairing is the process of connecting a *Bluetooth* product to a *Bluetooth* enabled device. This process only needs to be completed one time with each new device.

Pairing to 1 device:
1. Press and hold the multi-function button for about 8 seconds, until the indicator light alternates between blue and red, indicating that it is in pairing mode.
2. Activate the *Bluetooth* search feature on your phone, refer to your phone's manual for further instructions.
3. Select AA-2080 from the searched device listing.
4. Enter pin code "0000" to confirm and finish pairing. The headset will flash just blue to indicate completed pairing.

Pairing to 2 devices:
This headset contains a dual-link function for connecting with 2 mobile phones simultaneously.
1. Pair the first phone following the steps above.
2. Temporarily turn off the first connected phone's *Bluetooth* wireless technology function.
3. Pair the second phone using the steps above.
4. Turn off the headset, and re-turn on the first phones *Bluetooth* wireless technology functionality.
5. Re-turn on the headset, and it will re-connect to both devices automatically.

General Functions:

Turning On:
Press and hold the multi-function button for 5 seconds, indicator light will flash blue 3 times.
NOTE: For the first 5 cycles of turning on the headset, the headset will beep twice, and then flash blue 5 times, and then two times.

Turning Off:
Press and hold the multi-function button for 5 seconds, the headset will beep 3 times, and the indicator light will flash red 3 times.

Voice Dialing:
Press the multi-function button.

Redialing:
Press the multi-function button twice.

Answering/Ending a Call:
Press the multi-function button once.

Mute On/Off:
Press and hold Volume (-) for 2-3 seconds.

*Some functions may or may not work with certain phone models. See your phone's manual for more information.

Charging The Headset:
This headset includes a built-in Lithium Polymer battery. To charge the unit:
1. Plug the charger into proper outlet.
2. Plug the unit end of charger into the power outlet of headset.
3. During charging, the indicator light will turn red. When charging is complete, the indicator light will shut off or flash red to alert you that the headset is fully charged.

NOTE:
* For first time use, make sure to fully charge the headset at least for 4 hours, or preferably overnight (8-10 hours).
* If headset has not been used for more than 21 days, recharge unit for at least 4 hours or preferably overnight (8-10 hours).
* Do not use the headset during charging.
* Please only use original charger included in the packaging.
* If indicator light flashes red during usage or while on standby, the battery is low, and you should recharge the unit as soon as possible.
* Recharge unit only in places at room temperature.

Wearing The Headset:
This headset can be worn according to your preference, just adjust the microphone.