


19

C16



20

P1x2 P7

60mm

1:1


A10x2

E7x2

F33x7

P1x2

P7



21

A11

E3

E5

E6


E17

E18

P10

P11

P12_{x2}



22

A12

C17

C18




23

A13

A14

E14

G4 x4



24


A15

E2

E10

P1 x2

P4



25



A16 x2

C19 x2

G5 x4

P1 x2

P4



26

A17

E1

E11

P1×2



P6

P1×2



P6

30mm

1:1






P1



27



Scan for motion
assembly instruction.



28


C20

C21

C22


C23

C20



C21

C22



29

C24

C25

E8

E9

G6 x2

P1 x3

P3




Scan for motion assembly instruction.



P1 x3





P3




1:1



E8



E9



30

A18

A19

A20


E12

E13

E15

E16

G1 x4




31

A21

F1

G1 x2




32

A22

F2

F3

G2 x2




33

A23

A24

A25



34


A26

F4

F5

G1

G2




35

A27

F6

G1 x2




36

A28

A29

F7

G1 x2




37

A30

C26

F8

G1 x2




38


A31

F9

G1 x2




39




40

A32
F11
G1 x2




41

F12
A33
G1 x2



42




43

A34

F13

G1 x2




44

A35

F10

G1 x2




45

A36

F14

G1




46

A37

F15

G1 x2



47

A38 x2

A39 x2

C27

P1 x2

P9

